



**User
Manual
Version 12**



www.PEWeldBank.com

info@peweldbank.com



Page Contents

4	Subscribe to Fusion Management System (FMS).
5	Subscription Rates
6	How to login to the Fusion Management System (FMS)
7	Set up Company Details
8	Set up Users
9	Set up Butt Welding and Electrofusion Machines
9	Set up Pipe & Fitting Manufacturers
10	Set up Projects / Jobs
10	Review Active Sensors
11-17	FMS Reporting System
18	Smartphone / Tablet User Guide
19	Download PEWeldBank app from Google Play, Apple App store
19	Smartphone / Tablet Login
20	Smartphone / Tablet Home Screen
21-25	Smartphone / Tablet Menu Screens
26-30	Connection to Hydraulic circuit
31-33	Connection to Heater Plate
34-37	Pairing sensors to Phone or Tablet
38-55	Welding Procedure for App
56-58	Basic Welding Machine Operating Procedure
59-61	Review welds and add second GPS location
62-64	Troubleshooting
65	Calibration Details
66-75	Appendix 1: Connection of Hydraulic test point
76-79	Appendix 2: Updating Sensor Firmware
80-83	Appendix 3: Connection to Heater Plate via PT100 internal sensor
84	Appendix 4: User Hierarchy
85-87	Appendix 5: Unsubscribe or Resubscribe PEWeldBank FMS
88-90	Appendix 6: Resubscribing or Changing Credit Card Details
91-95	Appendix 7: Reviewing welds



Fusion Management System (FMS)

www.PEWeldBank.com


info@peweldbank.com

How to Subscribe to **PEWeldBank** Fusion Management System (FMS) on your PC or Laptop



You must subscribe to “PE Weld Bank Enterprise Multi User” if you want to use sensors

1. Go to **PEWeldBank.com** on your PC or Laptop
2. Click on Get Started



3. Click “Sign up”

[Sign in](#) [Sign up](#)

Sign Up

Get registered using your preferred package

Package <input type="text" value="PEWeldBank Enterprise Trial"/>	Welder Number <input type="text" value="Welder Number"/>
Username <input type="text" value="Username"/>	Phone <input type="text" value="Phone"/>
<small>Please enter username</small>	
Company Name <input type="text" value="Company Name"/>	Country <input type="text" value="Country"/>
First Name <input type="text" value="First Name"/>	Password <input type="password" value="Password"/>
Last Name <input type="text" value="Last Name"/>	<small>Please enter password</small>
Email <input type="text" value="Email"/>	Confirm Password <input type="password" value="Confirm Password"/>

Subscription Rates

Go to PEWeldBank.com for the current subscription features, details and prices.

“Standard” - AUD 5

This allows the user to calculate Butt Weld Time and Pressure parameters and steps them through the welding process with active timers and alarms. It stores weld information for up to three months.

“Enterprise” - AUD15* per user per month


This includes standard features and includes the ability to store Butt and Electrofusion weld data and connect to Bluetooth Sensor sets for active data recording.

This level also allows for multiple user reports to be stored together within a company database.

How to set up Company Details

Step 1, Click on Settings

Enter your Company Details. You can also insert a company logo here, this will be displayed on your reports



The screenshot shows the PEWELDBANK | FMS user interface. The top navigation bar is orange and contains the user name 'Darren Poynton'. The left sidebar is dark grey and lists various menu items: Dashboard, Projects, BW Machines, Pipe Manufacturers, Reports, Users, and Settings. A hand icon is pointing to the 'Settings' menu item. The main content area is divided into two sections: 'Company Profile' and 'Package Information'. The 'Company Profile' section contains several input fields: Name (Your Company), Address (Your Address), Phone (0410108101), Email (info@peweldbank.com), Manager Name (Your Managers Name), and Manager Phone (0418108101). There is also a 'Company Logo' field with a 'Drop Image here' instruction. The 'Package Information' section displays: Package (PEWeldBank Fusion Logger (5 Users)), Payment Term (Yearly), Subscribed Date (Monday 15th of April 2019), and Account Status (Active). There are buttons for 'Change your package', 'Edit', and 'Delete'.

Note there are 3 levels of users access;


- **Super admin** - This is the person that initially set the system up, they control company details, quantity of users, credit card etc. this user has access to all levels. To change Super admin user they must send an email to info@peweldbank.com and nominate the new Superadmin user from the user list, PEWeldBank will change this ASAP
- **Admin** - Controls adding / deleting, Projects, Users, Butt and Electrofusion machinery, pairing of sensors, pipe manufacturers
- **Welder** - Select projects, machines, pipe and welding standard, use of app to conduct welding

For more information regarding User Hierarchy, see Appendix 4

Set up Users (welder / admin)

Step 2, Click on Users

Set up User Details. You can allocate a User “Welder” or “Admin” rights




Welder Number	First Name	Last Name	Username	Email	Phone	User Status
P5001	Melissa	Poynton	info@polysmart.com.au	info@polysmart.com.au	0419108101	Active
P5078	Darren	Poynton	Darren002	darren@polysmart.com.au	0418108101	Active
P5833_old	David	Simons	sales3_old@fhs.com.au	sales3_old@fhs.com.au	0417361052	Active

How to set up Butt Welding and Electrofusion Machines

Step 3, Click on BW Machines or EF Units

Set Up your Butt Welding Machines or Electrofusion Control Units



PEWELDBANK | FMS Darren Poynton

Dashboard / Butt Welding Machines

[+ Add Machine](#) [CSV](#) [Excel](#) [Help](#) [Refresh Data](#)

Search:


<input type="checkbox"/>	Make	Model	Serial Number	Plant No / ID	Machine Status	Actions
<input type="checkbox"/>	Dixon	E/HF225	DX001	PS001	Active	
<input type="checkbox"/>	Dixon	E/HF355	DX002	PS002	Active	
<input type="checkbox"/>	fusion	gater313	123	123	Inactive	
<input type="checkbox"/>	Fusion	Gator 315	0441-T	RAD001	Active	
<input type="checkbox"/>	MAKO	Mako 200	Mako1	Mako1	Inactive	
<input type="checkbox"/>	McElroy	412 MF	MC001	PS005	Active	

Version 1.14

Set up Pipe & Fittings Manufacturers

Step 4, Click on Pipe Manufacturers

Set Up your Pipe and Fittings Library



PEWELDBANK | FMS Darren Poynton

Dashboard / Pipe Manufacturers

[+ Add Manufacturer](#) [CSV](#) [Excel](#) [Help](#) [Refresh Data](#)


Search:

<input type="checkbox"/>	Manufacturer Name	Created By	Manufacturer Status	Actions
<input type="checkbox"/>	APS	David Simons	Active	
<input type="checkbox"/>	Iplex Pipelines	Darren Poynton	Active	
<input type="checkbox"/>	Long Black Holes P/L	Darren Poynton	Active	
<input type="checkbox"/>	Plasson	David Simons	Active	

Showing 1 to 4 of 4 entries First Previous Next Last

Set up Projects / Jobs

Step 5, Click on Projects
Set Up Project Details



PEWELDBANK | FMS Darren Poynton

Dashboard / Projects


[+ Add Project](#) [CSV](#) [Excel](#) [Help](#) [Refresh Data](#)

Search:

<input type="checkbox"/>	Project Name	Project Location	Head Contractor	Project Owner	Project Status	Actions
<input type="checkbox"/>	Fault simulation	seaford	Darren	Darren	Inactive	
<input type="checkbox"/>	Filter Manifolds	Seaford	GoPoly	Irrigation Filters	Active	
<input type="checkbox"/>	Mains upgrade 123	Westown	PE Pipe Engineering	Mid West Water Corporation	Active	

Review active sensors

Step 6, Click on Sensors



PEWELDBANK | FMS Darren Poynton

Dashboard / Sensors

[Help](#) [Refresh Data](#)

Search:

Sensor ID	Calibration Date	Sensor Type	Sensor Status	Created Time	Actions
E3973310-44BD-195D-94B5-895D54C2DE16	30-10-2020	Pressure	Active	11-11-2020 14:44:15	
BCF614A7-AAD0-DF45-A8FB-CE5F4778063B	05-10-2020	Temperature	Active	27-10-2020 13:23:32	
B4:E62D:8C:B6:EB	17-06-2020	Temperature	Active	26-07-2020 14:00:04	



FMS


Reporting System

www.PEWeldBank.com

info@peweldbank.com

Reports

There are multiple reports and sort functions available, you can use one or multiple search features at the same time.




Welding Reports Summary

Total Welds	1007
For Review	799
Rejected	62
Reviewer Accepted	53
FMS Accepted	93

Weld Number	Custom Weld Number	Start Time	Operator	Pipe Size	SDR	Wall Thickness	Machine RAM	Project Name	Actions	Tags	Pressure and Time	Heater plate temperature	IS Cooling time adjusted by user	Accepted/Rejected Review	Operator Notes (from APP)	Reviewer Notes
23-12-2022																
20221023123718016	76	12:32	Poly Welder	110 mm	21	52 mm	164.7 mm ²	SoCal Trials					No			
20221023123718016	75	12:30	Poly Welder	110 mm	21	52 mm	164.7 mm ²	SoCal Trials					No			
30-11-2022																
20221030103980016	00748	13:41	Darren Paynter	160 mm	17	94 mm	164.7 mm ²	SoCal Trials					Yes	Auto by FMS		N/A

Reports

There are multiple reports and sort functions available



On the welding reports page the user can see a list of all welds and create a customised report by one or multiple search headings, then you can select a 4-5 page full report or “Short” or “Long” Reports or export all reports to your own back ups or excel, from this area you can send selected reports directly to you client.

Search Heading	Search Description
Machine Type	Butt Welder or Electrofusion
Project	Project Name
Machine	Make and Model of machine
Welder	The user or person doing the welding
Search	ID/ Spool Number / Drawing Number / Line Number
Weld Status	Status of weld i.e. Accepted, Rejected or waiting for Review
Welding Duration	Select time frame
Tags	Select tagged reports

Reports – Full 4-5 page report

There are multiple reports and sort functions available within the FMS, below is an example of the full 4-5 page report.


GoPoly Pty Ltd
 PO BOX 509
 Patterson Lakes
 VIC 3197
 darren@GOPOLY.com.au
 0418108101

PEWeldBank Individual Weld Report

Date	Weld Number	Start Time	Ambient Temp	Status
16-03-2022	2022031609448597	09:47	23.9° C	FMS Accepted

Weld Details	Required	Actual	Unit
P3 bead-up pressure	39.3-48.4	43.3-43.9	bar
T3 bead-up time	1-48	30.00	Seconds
P2 heat soak pressure	6.0-5.0	0.2-0.2	bar
T2 heat soak time	113-241	127	Seconds
T2 heater plate removal time	48	8	Seconds
T4 time to achieve fusion jointing pressure	47	47	Seconds
P3 fusion jointing pressure	39.3-48.4	41.8-42.1	bar
T3 cooling time in machine under pressure	247-00	00.00	Min:Sec

*Recommended cooling time has been adjusted by user



Welding Standard
 Standard name: ISO 21307 Single Low Pressure

Welding Company Details

Name	Contact	Phone
GoPoly Pty Ltd	Darren Poynton	0418108101

Operator Details

Operator	ID Number	DOB	App Version
Darren Poynton	P9098	28-03-1961	2.2.3

Pipe / Fitting Details

Material	Manufacturer	Type	Shape	Ø	SDR	Ø	Batch No.
Spigot 1	Iplex Pipelines	PE100	Pipe	160	17	9.4	1235566
Spigot 2	Iplex Pipelines	PE100	Pipe	160	17	9.4	1235566

Machine Details

Brand	Model	Ram Size	Serial No.	Calibration Date
Ribmo	Basic 160	194.7 mm³	13500013C 13500013F 13500013F	27-08-2021

Sensor Details

Spigot	Model	Serial No.	Calibration Date	Firmware Version
PEWeldBank Pressure	PWB-P133	30-AE-A4-F3-AE-DE	15-11-2021	V 1.3.8
PEWeldBank Temperature	PWB-T102	30-AE-A4-55-CE-A2	31-08-2021	V 1.0.7

Project Details

Project Name	Job Name	Project Contact Details
test 3	test	test 1234567890

Asset Details

Drawing Number	Spool Number	Line Number
12356	35776	2467

GPS Coordinates at Time of Completed Weld

Longitude	Latitude
145.13582	-38.112098


Heater Plate Target (°C)

	Front	Back
Zone 1	223	223
Zone 2	222	226
Zone 3	225	224
Zone 4	224	227
Average	224.16	
Fixed Point Sensor	228-230	

At commencement of weld
 Measured during Phase 1 and 2

Quality / Process Checklist

Is weld area protected?	Yes
Have the pipes been cleaned before placing in machine?	Yes
Are pipe ends covered?	Yes
Is pipe faced correctly?	Yes
Have pipe faces been cleaned?	Yes
Have pipe ends been checked for gap?	Yes
Is pipe aligned within 10% of wall thickness?	Yes



Notes
 Good test weld



Statement
 I, Darren Poynton, agree that I completed this weld correctly and completed checklists honestly.



OH&S Take 5

STOP (Ask Yourself)

Am I aware of existing points? (hydraulic movement)	Yes
Am I aware of sharp objects? (facing blades)	Yes
Am I aware of burning? (heating plate)	Yes
Have I protected myself from energy sources? (electrical, hydraulic, temperature)	Yes

THINK

Is a procedure or work instruction exists for the job am I familiar with it?	Yes
Am I trained, competent and authorised to do the job?	Yes
Do I have fit for purpose tools, equipment and PPE?	Yes
Can I control the risks associated with my task that affect the health and safety of myself or those around me and/or impact the environment?	Yes
If a permit is required for the job has a JSA or SWM etc. been completed?	Yes

IDENTIFY

Have I identified all the hazards and existing controls for the job?	Yes
Have I identified all the hazards and existing controls in the surrounding areas?	Yes

CONTROL

Am I satisfied existing controls are adequate?	Yes
--	-----

PROCEED - PERFORM THE TASK SAFELY

N.B. Ambient Temperature.
 Please note that the ambient temperature sensor is within the Pressure Sensor case, This temperature may be influenced by external factors, such as proximity to hydraulic motor, direct sunlight and charging of battery.

Reports – Short, long and export to excel

There are multiple reports and sort functions available within the FMS, below is an example of a short report and long report and below them is an example of an excel report

GoPoly Pty Ltd
PO BOX 509
Patterson Lakes
Vic 3197
darren@peweldbank.com.au
0418108101


PEWeldBank Weld Summary (Short)

Date	Weld Number	Start Time	Operator	Pipe Size	SDR	Job number
29-03-2022	202203291738668	17:53	Darren Poynton	63 mm	11	12341234
29-03-2022	202203291749868	17:49	Darren Poynton	63 mm	11	12341234
29-03-2022	202203291738668	17:38	Darren Poynton	63 mm	11	12341234
29-03-2022	202203291738668	17:33	Darren Poynton	63 mm	11	12341234
29-03-2022	202203291725868	17:25	Darren Poynton	63 mm	11	12341234
29-03-2022	202203291720868	17:20	Darren Poynton	63 mm	11	12341234
28-03-2022	202203281658868	16:58	Darren Poynton	160 mm	17	12341234
28-03-2022	202203281378668	13:37	Darren Poynton	160 mm	17	12341234
27-03-2022	2022032712018822	12:01	Darren Poynton	160 mm	17	PO01
27-03-2022	20220327085285977	08:53	Darren Poynton	160 mm	17	test1
25-03-2022	20220325090485977	09:04	Darren Poynton	160 mm	17	test1
22-03-2022	20220322103785977	10:37	Darren Poynton	160 mm	17	test1
21-03-2022	2022032102185977	20:23	Darren Poynton	160 mm	17	test1
18-03-2022	20220318131485977	13:17	Darren Poynton	160 mm	17	test1
16-03-2022	2022031611185977	11:15	Darren Poynton	160 mm	17	test1
16-03-2022	20220316094485977	09:44	Darren Poynton	160 mm	17	test1
15-03-2022	20220315065685977	06:56	Darren Poynton	160 mm	17	test1
10-03-2022	20220310142885977	14:28	Darren Poynton	160 mm	17	test1
10-03-2022	20220310142085977	14:20	Darren Poynton	160 mm	17	test1
09-03-2022	20220309130485977	13:05	Darren Poynton	125 mm	11	test1
08-03-2022	20220308115885977	12:00	Darren Poynton	125 mm	11	test1
07-03-2022	20220307133685977	13:37	Darren Poynton	160 mm	17	test1
07-03-2022	20220307134685977	13:26	Darren Poynton	160 mm	17	test1
04-03-2022	20220304103985977	10:39	Darren Poynton	160 mm	17	test1
04-03-2022	20220304102685977	10:26	Darren Poynton	160 mm	17	test1
04-03-2022	20220304101085977	10:10	Darren Poynton	160 mm	17	test1
04-03-2022	20220304095985977	09:58	Darren Poynton	160 mm	17	test1
04-03-2022	20220304091185977	09:11	Darren Poynton	160 mm	17	test1
03-03-2022	2022030320285977	23:02	Darren Poynton	160 mm	17	test1

GoPoly Pty Ltd
PO BOX 509
Patterson Lakes
Vic 3197
darren@peweldbank.com.au
0418108101

PEWeldBank Weld Summary (Long)


Date	Weld Number	Start Time	Operator	Pipe Size	SDR	Wall Thickness	Machine RAM	Job number
29-03-2022	202203291738668	17:53	Darren Poynton	63 mm	11	5.7 mm	626 mm²	12341234
29-03-2022	202203291749868	17:49	Darren Poynton	63 mm	11	5.7 mm	626 mm²	12341234
29-03-2022	202203291738668	17:38	Darren Poynton	63 mm	11	5.7 mm	316 mm²	12341234
29-03-2022	202203291738668	17:33	Darren Poynton	63 mm	11	5.7 mm	194.7 mm²	12341234
29-03-2022	202203291725868	17:25	Darren Poynton	63 mm	11	5.7 mm	194.7 mm²	12341234
29-03-2022	202203291720868	17:20	Darren Poynton	63 mm	11	5.7 mm	194.7 mm²	12341234
28-03-2022	202203281658868	16:58	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	12341234
28-03-2022	202203281378668	13:37	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	12341234
27-03-2022	2022032712018822	12:01	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	PO01
27-03-2022	20220327085285977	08:53	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
25-03-2022	20220325090485977	09:04	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
22-03-2022	20220322103785977	10:37	Darren Poynton	160 mm	17	10.0 mm	194.7 mm²	test1
21-03-2022	2022032102185977	20:23	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
18-03-2022	20220318131485977	13:17	Darren Poynton	160 mm	17	10.0 mm	194.7 mm²	test1
16-03-2022	2022031611185977	11:15	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
16-03-2022	20220316094485977	09:44	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
15-03-2022	20220315065685977	06:56	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
10-03-2022	20220310142885977	14:28	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
10-03-2022	20220310142085977	14:20	Darren Poynton	160 mm	17	9.4 mm	194.7 mm²	test1
09-03-2022	20220309130485977	13:05	Darren Poynton	125 mm	11	11.0 mm	753 mm²	test1




A1	Date	Weld Number	Start Time	Ambient	Result	CP	P1	Min	Re	P1	Max	Ac	P1	Min	Re	P1	Max	Ac	T1	Requ	T1	Actual	P2	Min	Re	P2	Max	Ac	P2	Min	Re	P2	Max	Ac	T2	Requ	T2	Actual	P3	Min	Re	P3	Max	Ac	P3	Min	Re	P3	Max	Ac	T3	Requ	T3	Actual	P4	Min	Re	P4	Max	Ac	T4	Requ	T4	Actual	P5	Min	Re	P5	Max	Ac	T5	Requ	T5	Actual	P6	Min	Re	P6	Max	Ac	T6	Requ	T6	Actual	P7	Min	Re	P7	Max	Ac	T7	Requ	T7	Actual	P8	Min	Re	P8	Max	Ac	T8	Requ	T8	Actual	P9	Min	Re	P9	Max	Ac	T9	Requ	T9	Actual	P10	Min	Re	P10	Max	Ac	T10	Requ	T10	Actual	P11	Min	Re	P11	Max	Ac	T11	Requ	T11	Actual	P12	Min	Re	P12	Max	Ac	T12	Requ	T12	Actual	P13	Min	Re	P13	Max	Ac	T13	Requ	T13	Actual	P14	Min	Re	P14	Max	Ac	T14	Requ	T14	Actual	P15	Min	Re	P15	Max	Ac	T15	Requ	T15	Actual	P16	Min	Re	P16	Max	Ac	T16	Requ	T16	Actual	P17	Min	Re	P17	Max	Ac	T17	Requ	T17	Actual	P18	Min	Re	P18	Max	Ac	T18	Requ	T18	Actual	P19	Min	Re	P19	Max	Ac	T19	Requ	T19	Actual	P20	Min	Re	P20	Max	Ac	T20	Requ	T20	Actual	P21	Min	Re	P21	Max	Ac	T21	Requ	T21	Actual	P22	Min	Re	P22	Max	Ac	T22	Requ	T22	Actual	P23	Min	Re	P23	Max	Ac	T23	Requ	T23	Actual	P24	Min	Re	P24	Max	Ac	T24	Requ	T24	Actual	P25	Min	Re	P25	Max	Ac	T25	Requ	T25	Actual	P26	Min	Re	P26	Max	Ac	T26	Requ	T26	Actual	P27	Min	Re	P27	Max	Ac	T27	Requ	T27	Actual	P28	Min	Re	P28	Max	Ac	T28	Requ	T28	Actual	P29	Min	Re	P29	Max	Ac	T29	Requ	T29	Actual	P30	Min	Re	P30	Max	Ac	T30	Requ	T30	Actual	P31	Min	Re	P31	Max	Ac	T31	Requ	T31	Actual	P32	Min	Re	P32	Max	Ac	T32	Requ	T32	Actual	P33	Min	Re	P33	Max	Ac	T33	Requ	T33	Actual	P34	Min	Re	P34	Max	Ac	T34	Requ	T34	Actual	P35	Min	Re	P35	Max	Ac	T35	Requ	T35	Actual	P36	Min	Re	P36	Max	Ac	T36	Requ	T36	Actual	P37	Min	Re	P37	Max	Ac	T37	Requ	T37	Actual	P38	Min	Re	P38	Max	Ac	T38	Requ	T38	Actual	P39	Min	Re	P39	Max	Ac	T39	Requ	T39	Actual	P40	Min	Re	P40	Max	Ac	T40	Requ	T40	Actual	P41	Min	Re	P41	Max	Ac	T41	Requ	T41	Actual	P42	Min	Re	P42	Max	Ac	T42	Requ	T42	Actual	P43	Min	Re	P43	Max	Ac	T43	Requ	T43	Actual	P44	Min	Re	P44	Max	Ac	T44	Requ	T44	Actual	P45	Min	Re	P45	Max	Ac	T45	Requ	T45	Actual	P46	Min	Re	P46	Max	Ac	T46	Requ	T46	Actual	P47	Min	Re	P47	Max	Ac	T47	Requ	T47	Actual	P48	Min	Re	P48	Max	Ac	T48	Requ	T48	Actual	P49	Min	Re	P49	Max	Ac	T49	Requ	T49	Actual	P50	Min	Re	P50	Max	Ac	T50	Requ	T50	Actual
29-03-2022	202203291738668	17:53	22	No	8.9	12.2	10.5	10.6	1	14	0	2	0	0.5	57	68	63	6	6	0	0	0	8.9	12.2	10.3	10.7	20	20	20	2.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
29-03-2022	202203291749868	17:49	21	No	8.9	12.2	10.4	10.7	1	19	0	2	0.1	0.8	57	68	63	6	6	0	0	0	8.9	12.2	10.2	10.7	20	20	2.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
29-03-2022	202203291738668	17:38	21	No	18.7	25.2	20.5	20.9	1	21	0	5	0.5	1.7	57	68	63	6	6	0	0	0	18.7	25.2	20.4	20.7	10	10	5.7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
29-03-2022	202203291738668	17:33	21	No	27.2	37.8	0.8	31.1	1	43	0	5	0	1.1	57	68	63	6	6	0	0	0	27.2	37.8	0.9	1.5	02:28	01:30	6.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
29-03-2022	202203291725868	17:25	20	No	27.2	37.8	32.1	33.2	1	17	0	5	0.1	1.8	57	68	63	6	6	0	0	0	27.2	37.8	32.1	33	02:28	00:19	6.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
29-03-2022	202203291720868	17:20	18	No	27.2	37.8	29.3	30.1	1	24	0	5	0.1	1.7	57	68	63	6	6	0	0	0	27.2	37.8	29.2	29.8	10	10	6.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
28-03-2022	202203281658868	16:58	22	Yes	42.8	51.9	46.3	47.8	1	50	0	8.5	0.4	2.9	112	141	127	8	8	7	7.8	42.8	51.9	45.7	47.1	12:25	12:25	13.7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
28-03-2022	202203281378668	13:37	21	Yes	42	51.1	46.2	47.3	1	55	0	7.7	2.3	4.3	112	141	127	8	8	7	7.8	42	51.1	48	49.4	12:25	12:25	12.9																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
27-03-2022	2022032712018822	12:01	-	N/A	39.2	48.4	-	-	1	-	0	5	-	-	113	141	-	-	-	-	0	39.2	48.4	-	-	15	-	10.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
27-03-2022	20220327085285977	08:53	-	N/A	36.2	45.4	-	-	1	-	0	2	-	-	113	141	-	-	-	-	0	36.2	45.4	-	-	12:25	-	7.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
25-03-2022	20220325090485977	09:04	-	N/A	39.2	48.4	-	-	1	-	0	5	-	-	112	141	-	-	-	-	0	39.2	48.4	-	-	12:25	-	10.2																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
22-03-2022	20220322103785977	10:37	25	No	43.1	52.8	44.8	47	1	95	0	6.8	1.5	3.9	120	150	135	8	8	7	7.8	43.1	52.8	45.9	46.7	10	10	12.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
21-03-2022	2022032102185977	20:23	-	N/A	44	56	-	-	0	-	0	5	-	-	30	30	-	-	-	-	0	44	56	-	-	20	-	0																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																

Reports - Email directly to client

The email report option allows you to select welds and then email them to your client. Please note these reports take a short while to generate, if it doesn't come through please ask your client to check their junk or spam box



Your client will receive email similar to this, with 3 options for viewing reports



See 3 report options on next page

Reports - Email directly to client

The first one is a summary.




Darren Poynton
GoPoly Pty Ltd
PO BOX 509
Patterson Lakes
Vic 3197
darren@gopoly.com.au
0418108101


PEWeldBank PEWeldBank Weld Summary (Email)

Weld Number	Start Time	Operator	Pipe Size	SDR	Wall Thickness	Machine RAM	Project Name
29-03-2022							
2022032917328668	17:33	Darren Poynton	63 mm	11	5.7 mm	194.7 mm ²	Mains upgrade 123
28-03-2022							
2022032816588668	16:58	Darren Poynton	160 mm	17	9.4 mm	194.7 mm ²	Mains upgrade 123
2022032813378668	13:37	Darren Poynton	160 mm	17	9.4 mm	194.7 mm ²	Mains upgrade 123

The second is a Zip file holding of each selected weld each PDF is a full 4-5 page report.









The third option gives your client a full report for each weld and access to the weld graph



PEWELDBANK | FMS

Buttt Welding Reports

? Help

Weld Number	Start Time	Operator	Pipe Size	SDR	Wall Thickness	Machine RAM	Project Name	Actions
29-03-2022								
2022032917328668	17:33	Darren Poynton	63 mm	11	5.7 mm	194.7 mm ²	Mains upgrade 123	 
28-03-2022								
2022032816588668	16:58	Darren Poynton	160 mm	17	9.4 mm	194.7 mm ²	Mains upgrade 123	 
2022032813378668	13:37	Darren Poynton	160 mm	17	9.4 mm	194.7 mm ²	Mains upgrade 123	 



Smartphone / Tablet User Guide

www.PEWeldBank.com


info@peweldbank.com

Download *PEWeldBank* app in your preferred store for FREE

Go to search on Google Play or Apple App store enter “peweldbank”



Once downloaded to your Smartphone or tablet, click on the *PEWeldBank* icon



Use your Username and Password to log in, this will take you to the home screen.



Home Screen

Operation is very easy to access via the Home Screen

Drop Down Menu




Tap here to start a Butt weld



Tap here to start an Electrofusion weld





Tap here to review weld




Smartphone / Tablet - Default System Settings

Click on dropdown menu



Click on menu item




Select **System Settings** to Edit Settings



Smartphone / Tablet - Default System Settings

Select your preferred defaults before welding

These changes can only be made by user with Superadmin or Admin level



The screenshot shows the 'System Settings' screen with the following sections:

- SYSTEM OF MEASUREMENT**: Three buttons: IMPERIAL DIPS, IMPERIAL IPS, and METRIC (selected).
- TAKE FIVE CHECKLIST**: Two buttons: ENABLE and DISABLE (selected).
- CHECK HEATER PLATE TEMPERATURE**: Three buttons: Automatically, Manually (selected), and Off.
- TEMPERATURE WARNINGS**: Two buttons: ENABLE and DISABLE (selected).
- MANUAL OVERRIDE MODE**: Two buttons: ENABLE and DISABLE (selected). Below the buttons, it says: "This allows the user to initiate start in Phases 1, 2 & 5".
- System Language**: A dropdown menu showing 'English'.
- CUSTOM WELD NUMBER**: Two input fields: 'Prefix' (empty) and 'Starting Number' (0). Below these is a 'RESET' button.

SYSTEM OF MEASUREMENT

Choose preferred measurements

TAKE 5 CHECK LIST

By enabling this, the app will ask the user to complete Welding Safety questions at the start of a weld session

CHECK HEATER PLATE TEMPERATURE

By enabling this, the app will ask the user to check heater plate temperature at selected intervals or turn this feature off.

TEMPERATURE WARNINGS

When enabled user will be notified if temperature goes out of range

MANUAL OVERRIDE MODE

This enables to initiate start in Phases 1, 2 & 3


SYSTEM LANGUAGE

Enables user to choose different languages

CUSTOM WELD NUMBER

Set smartphone custom weld number series



Smartphone / Tablet - Settings




All of these options except for Sensors, System Settings and some of the Operator Details can also be edited via the FMS

Smartphone / Tablet Menu Screens ADDING NEW PROJECT


Click on dropdown menu




Click on menu item



Select **Projects** to Edit or Add New Projects




Select **Settings** to Edit Settings




Smartphone / Tablet Menu Screens **ADDING NEW MACHINE**


Click on dropdown menu




Click on menu item



Select **Butt welding Machines** to Edit



Select **ADD NEW** to Edit or Add New Butt Welder





Connection to Hydraulic circuit

www.PEWeldBank.com

info@peweldbank.com

Fitting Hydraulic Transmitter / Transducer to Machine




Hydraulic Connection



Many machines have a test port already fitted.

If your machine does not have a test point, you will need to fit a tee with test point to **the closing side of your pressure circuit.**

A tee with connection point can be fitted to a machine where the hoses are fitted to the pressure control unit. Any hydraulic company should be able to fit one for you. See Appendix 1 for examples.



Note:

This is the closing side of the hydraulic cylinder, follow this hose back to your controller. As we set up more machines we will keep a library of connections, please don't hesitate contacting us for assistance with initial set up.

Bluetooth Pressure Sensor Setup

How to connect pressure sensor to Butt welder See also “Appendix 1”



****Before starting ensure both Sensors are fully charged****

Plug charge cable into charging port and charge until the red light turns to green (6 hours)


Pressure Sensor Components

- 1 Bluetooth Pressure Sensor
- 2 Hydraulic Transducer
- 3 Orange or Black Hydraulic Sensor Connection cable
- 4 Charging Port
- 5 Charging Indicator Light (Red/Green)
- 6 Bluetooth Connection Status Light (Blue)
- 7 Hydraulic connection
- 8 Hydraulic Sensor Port 1
- 9 Hydraulic Sensor Port 2 (Spare)
- 10 QR code

Connect orange cable here



On the Rear of both Sensors there is a **QR Code** that you scan to enable sensor when prompted by phone or tablet or just select connect to nearest sensor.



Hydraulic Connection Continued



Stauff 20 test point
available from your local
PEWeldBank reseller or hydraulics
supplier



The PEWeldBank Transmitter
This fits to the Stauff test point

Fit the PEWeldBank transmitter to the test point.
Now fit the Orange or Black cable supplied to the Bluetooth pressure sensor **Port 1**
as shown below.





Connection to Heater Plate

www.PEWeldBank.com

info@peweldbank.com

Temperature Sensors dated January 2020

Bluetooth Temperature Sensor Setup

How to use sensor with heater plate.



****Before starting ensure Sensors are fully charged****

Plug charge cable into charging port and charge until the red light turns to green (5 hours)

Pressure Sensor Components

- 1 Bluetooth Temperature Sensor
- 2 Surface Temperature Probe
- 3 Charging Port
- 4 Charging Indicator Light (Red/Green)
- 5 Bluetooth Connection Status Light (Blue)
- 6 Spare Port
- 7 Port for surface probe (marked Fixed)
- 8 QR code

Connect surface probe here



On the Rear of both Sensors there is a **QR Code** that you scan to enable sensor when prompted by phone or tablet



2



Temperature Sensors dated March 2022 & later

Bluetooth Temperature Sensor Setup

How to connect your Temperature Sensor to your heater plate. “See Appendix 3”



****Before starting ensure Sensors are fully charged****

Plug charge cable into charging port and charge until the red light turns to green (5 hours)

Pressure Sensor Components

- 1 Bluetooth Temperature Sensor
- 2 Surface Temperature Probe
- 3 Charging Port
- 4 Charging Indicator Light (Red/Green)
- 5 Bluetooth Connection Status Light (Blue)
- 6 Port for Surface probe
- 7 Port for Fixed PT100 connection
- 8 QR code
- 9a PT100 connection cable for Ritmo*
- 9b PT100 connection cable for others*



On the Rear of both Sensors there is a **QR Code** that you scan to enable sensor when prompted by phone or tablet

*see appendix 3





Pairing Sensors to Phone or Tablet

www.PEWeldBank.com


info@peweldbank.com

Bluetooth Setup & Pairing of Sensors


! *N.B. you can only use sensor set with **PEWeldBank Fusion Logger** subscription, For initial pairing you must also have administrator user level permission and connection to the internet*

Ensure that Bluetooth is enabled on your smartphone / tablet. Follow the prompts


1. Click **Dropdown Menu**



2. Click **Settings**



3. Click **Sensors**



4. Click **Add New**



Bluetooth Setup & Pairing of Sensors Continued

Pairing of Sensors


- Connect Pressure sensor to pressure at least 2 bar.
- For the Temperature sensor holding the Surface Temperature Probe against heater plate (at least 80°C / 176°F) will activate the sensor.
- The status light will flash, enabling you to proceed with Bluetooth pairing.

Alternatively

- Remove and replace the battery from the sensor, this will activate and status light will flash for 2 minutes enabling you to proceed with Bluetooth pairing.
- Status light must be flashing fast before proceeding.


Follow instructions in Dropdown menu on smartphone or tablet [settings] [sensors] [add new] [save]

Scan QR code:




Bluetooth Setup & Pairing of Sensors Continued

Click Save



Check connected sensor



Connected



When connected blue Light on the sensor will flash slowly



Click Drop down menu to return to home screen follow instructions again for second sensor



To remove a sensor from Phone or Tablet select sensor you want to remove and click and hold for 2 seconds then delete, for iOS swipe then delete




Welding Procedure for App

Also see Basic Welding Machine Operating Procedure

www.PEWeldBank.com




info@peweldbank.com

Home Screen: Commence Butt welding or Electrofusion



From this screen you can commence Butt welding or Electrofusion. You can also review previous welds or allocate a second GPS location

Select Project




From this screen you need to select a project.

The Projects can be set up from within this app or from the FMS.

Note: You must have Admin access to set up projects, however User or Admin may select a project to use.

Safety “Take Five”



The screenshot shows a mobile application interface for a safety assessment. At the top, there is a status bar with the time 4:51, signal strength, Wi-Fi, and battery icons. Below the status bar is an orange header with a menu icon, the text "Safety 'Take 5'", a welding mask icon, and "P: 80%". The main content is divided into two sections: "STOP (Ask yourself)" and "THINK".

STOP (Ask yourself)

- Am I aware of crushing points? (hydraulic movement) YES NO NA
- Am I aware of sharp objects? (facing blades) YES NO NA
- Am I aware of burning (heating plate) YES NO NA
- Have I protected myself from energy sources? (electrical, hydraulic, temperature) YES NO NA

THINK

- If a procedure or work instruction exists for the job am I familiar with it? YES NO NA
- Am I trained, competent and authorised to do the job? YES NO NA
- Do I have fit for purpose tools, equipment and PPE? YES NO NA
- Can I control the risks associated with




At the bottom of the screen, there is a dark brown bar with the text "PROCEED - PERFORM THE TASK SAFELY".

This is a 12 question OH&S assessment, these questions are asked from the user at the start of the welding session.

This information is collected and recorded within reports and are available within the FMS


By default this option is disabled, this option may be enabled within System Settings

Machine selection



From this screen you will need to select a Machine.
Machines can be added and edited from within this app or from the FMS.
Note: You must have Admin access to set up projects, however User or Admin may select a machine to use.
By selecting machine it will use stored hydraulic ram information for pressure calculations, and machine data in reports.

Pipe / Fitting selection

A screenshot of a mobile application interface for pipe selection. The screen has an orange header with a menu icon, the text 'Pipe / Fitting', a green icon of a pipe and fitting, and 'P: 80%'. Below the header are two tabs: 'PIPE/FITTING 1' (selected) and 'PIPE/FITTING 2'. The main area contains several input fields: 'Pipe/Fitting ^{dn} (mm)' with the value '160', 'SDR' with the value '17', '^{en} (mm)' with the value '9.41', 'Manufacturer', 'Batch Number', 'Type', and 'Profile'. A 'NEXT' button is at the bottom.

From this screen you will need to select a Pipe size and SDR, pipe wall thickness is automatically calculated but can be adjusted manually.


Manufacturer, Type and Profile Welds are optional.

Pipe data can be added and edited from within this app or from the FMS.

Note: You must have Admin access to set up projects, however User or Admin may select a machine to use.

By selecting machine it will use stored hydraulic ram information for pressure calculations, and machine data in reports.

Pre weld check list



The screenshot shows a mobile application interface for a 'Pre weld check list'. The top bar is orange with a menu icon, the title 'Check List', a green icon of a person with a tool, and 'P: 80%'. Below the bar are seven checklist items, each with a 'YES' button and a checkbox:


- IS WELD AREA PROTECTED? YES
- HAVE THE PIPES BEEN CLEANED BEFORE PLACING IN MACHINE YES
- ARE PIPE ENDS COVERED? YES
- IS PIPE FACED CORRECTLY? YES
- HAVE PIPE FACES BEEN CLEANED? YES
- HAVE PIPE ENDS BEEN CHECKED FOR GAP? YES
- IS PIPE ALIGNED WITHIN 10% OF WALL THICKNESS? YES

Below the checklist is a 'Photo' section with a camera icon and a photo of pipe alignment. At the bottom is a 'NEXT' button.

This check list has 7 optional questions, these questions default to NO and are included on reports, however you do not need to answer these to be able to move onto the next screen.

Upon selecting yes to the last question the camera will be activated to allow user to take a photo of pipe alignment and gap.

Parameters




The Parameters screen displays a review of pipe and machinery and asks user to enter preferred **welding standard**, this preference is set as a default until the start of a new session.

The **drag** also needs to be entered in this screen.

Note: The Pressure Gauge will be active only when sensor set is supplied and paired.


Check Heater plate



When connected to temperature sensor set, this screen automatically logs temperature during Bead up and heat soak phases, also using the supplied surface temperature probe the user can accurately record the surface temperature at the start of the welding session or at the start of every weld or turn to manual entry, .

This temperature recording options can be adjusted within system settings.

Calculation and Pressure Pre set



When connected to pressure sensor set, this screen automatically logs Ambient temperature and Humidity, if not connected to sensor set these can be added manually.

This screen also allows the user to manually adjust T5 cooling time to allow for Reduced cooling times or extending the time when allowance for rough handling is required. This adjustment is noted on weld reports!


Most importantly the user must set pressure for Phase 1 and Phase 5 at this point.

Phase 1: Bead up





Phase 1 screen instructs the user what to do and when to reduce pressure to Drag. Temperature can also be monitored during this Phase

Phase 2: Heat Soak



After bead up as soon as user drops to Drag pressure or below the Heat soak timer begins count down (the pressure is recorded during this phase)


Phase: 3. Heater Plate Removal



User is notified by a alarm to remove heater plate and bring ends back together within displayed time


Phase 4: Pressure up

(for high Pressure welding this Phase is incorporated within Phase 3)




User is notified by a alarm to bring ends back up to weld pressure within displayed time.

Phase 5 Cooling time in Machine under Pressure



Timer automatically starts for cooling time

Weld Completed




Once weld is completed the user is prompted to mark the unique weld number and welder id onto the pipe next to the weld
The unique number is made up from the following information.

Year				Month		Day		Hour		Minute		Part of user ID		FMS created from project	
2	0	2	2	0	3	2	8	1	3	3	7	8	6	6	8

The user is prompted to take a photo including the unique ID number of completed weld while still in machine.


The graph gives the user the opportunity to review the weld before progressing.

Location, Notes and Reporting



The GPS is automatically recorded and displayed in this screen
The User can also enter comments
And further Asset details including :
Drawing Number
Spool Number
Line number
There is an area here to include a ;
Sketch
Operator Identification Photo
Operator Signature
The information here is not compulsory except for the signature.

Do you wish to start another weld



At this point the user can choose to finish the session or continue to another weld, if they choose to continue they are taken back to the check list screen and all other data parameters are still set to the same as previous weld.
If the user chooses No the system returns to the Home screen




Basic Welding Machine Operating Procedure

www.PEWeldBank.com

info@peweldbank.com

Hydraulic Valve Control Sequence when using PEWeldBank (On demand flow)



Generic Pressure control unit. Most basic units run similarly but valves may be arranged differently.

After Facing, cleaning, alignment and Recording Drag pressure


1. Close Pressure Release Valve ①
2. Close carriage and set Pressure Set Valve ② to XX bar
3. Press **[NEXT]** on PEWeldBank.
4. Open carriage this will drop pressure to drag or less.
5. Insert Heater Plate.
6. Bring Pipe up to heater plate to XX bar pressure and hold Direction Lever for several seconds.
7. When you have bead up size
8. Reduce to 0-Drag Using Pressure Release Valve ①
And Wait for Heat Soak Time.
8. Open Carriage: Just enough to remove heater plate.
9. Remove Heater Plate and Close carriage, hold Direction Lever for several seconds.

(Continual flow:- Hydraulic pump runs continually,

On demand flow :- Hydraulic pump only runs when lever activated)

info@peweldbank.com

Valve Control Sequence when using PEWeldBank (Continual flow)



After Facing, cleaning, alignment and setting Heating / Drag pressure.

1. Close carriage and set Fusing pressure valve ③ to XX bar
2. Press **[NEXT]** on PEWeldBank
3. Open carriage **ALL THE WAY** this will drop pressure to drag or less.
4. Insert Heater Plate
5. Bring Pipe up to heater plate to XX bar pressure
6. When you have bead up size
7. Reduce to 0-Drag

To do this correctly you must move "Valve Selector" to 2 position and wait for pressure to drop to below drag, then move "Direction Lever" to neutral. And Wait for Heat Soak Time

8. Open Carriage; move "Valve Selector" down to Fusion Position 3, move "Direction Lever" to the right, just enough to remove heater plate.
9. Remove Heater Plate and Close carriage.
10. To avoid pressure spike, slow carriage speed just before closure.

(Continual flow:- Hydraulic pump runs continually,

On demand flow :- Hydraulic pump only runs when lever activated)




Review welds and add second GPS location

www.PEWeldBank.com

info@peweldbank.com


How to Review Welds on Smartphone or Tablet


Go to the **HOME SCREEN**
Click on **REVIEW WELDS**



Empty green circle indicates that weld has been recorded on Tablet / Phone, but is waiting to be uploaded to FMS

Full green circle indicates that the weld is recorded on Tablet / Phone *and* FMS



If you see a cloud icon this means this weld is only on the FMS but can be downloaded to the Tablet / Phone by clicking on icon 



How to Review Welds - Insert 2nd GPS Location


A valuable feature of **PEWeldBank** is the ability to add a 2nd GPS location. This is particularly useful where the installation location is different to where the welding was undertaken.

From the Review Welds screen (see previous page), select a weld you want to review or add the second GPS location.



The on-screen Report shows all information about this weld

Zoom into graph to see finer detail



Scroll down further to find the GPS location.

Click here to update weld location, this does not change original information it simply adds a second GPS location for this weld which will be available on reports.



Trouble shooting

www.PEWeldBank.com

info@peweldbank.com

Troubleshooting

Pressure Sensor		
Problem	Reason	Solution
No fast flashing blue status light on sensor	Sensor connected to wrong side of hydraulics	Make sure it is connected to closing side of hydraulics (this is generally the cylinder inlet closest to middle of machine see photo)
	Sensor not connected to hydraulic with	Connect transducer cable to transducer and sensor and increase pressure, fast flashing should start within 10 seconds
	Orange transducer connected to wrong port on sensor	Connect transducer cable to Port "1" on sensor
	Battery low or flat on sensor	Charge sensor until Charging light shines green
		Check operation of sensor by momentarily removing and replacing battery, Blue Status light should flash fast
Zero pressure reading on smartphone		Check above information
I have fast flashing blue light but wont connect to smartphone	Bluetooth turned off in smartphone	Turn Bluetooth to on in smartphone
		Smartphone must be connected to internet for initial pairing
	Camera disabled	Allow camera settings in smartphone
		Try connecting to nearest sensor rather than scanning qr code
	Not paired	Check in PEWeldBank on smartphone settings > sensors, your sensor should be listed here (check that the number matches number on sensor) delete any sensor not currently required
	Battery low or flat on sensor	Charge sensor until Charging light shines green
	Battery low or flat on smartphone	Charge smartphone
	Sensor not connected to	Check above information
Zero pressure reading on smartphone		Check above information
Pressure reading on Machine Gauge is different to smartphone	Machine Gauge is probably incorrect	All PEWeldBank transducers are highly accurate and calibrated when packed, if concerned have your gauge tested.

Troubleshooting

Temperature Sensor		
Problem	Reason	Solution
No fast flashing blue status light on sensor	Surface Probe not in contact with Hot heater plate	Hold Surface Probe against Hot heater plate for at least 10 seconds this will activate sensor
	Battery low or flat on sensor	Charge sensor until Charging light shines green
	Surface Probe not connected to correct port on sensor	Connect Surface probe to "Fixed" port on sensor
		Check operation of sensor by temporarily removing and replacing battery, Blue Status light should flash fast
I have fast flashing blue light but wont connect to smartphone	Bluetooth turned off in smartphone	Turn Bluetooth to on in smartphone
		Smartphone must be connected to internet for initial pairing
	Camera disabled	Allow camera settings in smartphone
		Try connecting to nearest sensor rather than scanning qr code
	Not paired	Check in PEWeldBank on smartphone settings > sensors, your sensor should be listed here (check that the number matches number on sensor) delete any sensor not currently required
	Battery low or flat on sensor	Charge sensor until Charging light shines green
	Battery low or flat on smartphone	Charge smartphone
Temperature reading on heater plate controller is different to smartphone	Surface probe must be held against heater plate	Hold Surface Probe against Hot heater plate for at least 10 seconds this will activate sensor
	Temperature reading is possibly incorrect or reading core temperature, not surface temperature	All PEWeldBank surface probes are accurate and calibrated when packed, if concerned have your heater plate independently tested.

Calibration Details

In accordance with
ASTM F3124-15. Standard Practice for
Data Recording the Procedure used to Produce Heat Butt Fusion Joints in
Plastic Piping Systems or Fittings.

GOPOLY Pty Ltd (the manufacturer of the PEWeldBank sensor set) recommends bi-annual calibration. However, local governance may have different requirements, so we suggest that you check with the relevant authorities in your area.

Pressure Transducers come with a 5-year performance guarantee from the instrument manufacturer, the Pressure Transducers can be tested / compared against qualified instruments.

Surface Temperature Probes come with a 2-year performance guarantee from the instrument manufacturer. The Surface Temperature Probes can be tested / compared against qualified instruments.

Independent Laboratory Testing / Calibration may be requested in some cases. If so, we recommend that you contact your local PE Weld Bank reseller or a local testing / calibration laboratory to calibrate Pressure Sensor / Transducer and Temperature Sensor / Surface Temperature Probe, or return to GOPOLY for this service.



Appendix 1



Connection of Hydraulic test point

www.PEWeldBank.com

info@peweldbank.com

Appendix 1a Ritmo Basic with steel case

N.B. first ensure that the power is disconnected & there is no pressure in system.
Remove hydraulic hose from control box (Closing pressure side)
Fit "Stauff Swivel run tee"
Fit hydraulic hose to "Stauff Swivel run tee"
Fit "Stauff Test point"
Fit PEWeldBank Transducer to Stauff test point 20.



Appendix 1b Ritmo Basic with Plastic case

N.B. Brst ensure that the power is disconnected & there is no pressure in system.

You will need to remove top cover from control box.

Remove hydraulic hose from control box

Fit item "1"


Fit hydraulic hose to item "1"

Fit item "19 to 1"


Drill hole into plastic case and Bt item "23"

Connect Line item 24 to item 19 and Line item "23"

Fit PEWeldBank Transducer to item "23"



Line item "1"





Appendix 1c Dixon EHF 225 & 350

N.B. first ensure that the power is disconnected & there is no pressure in system.
Remove male quick connect fitting and washer leaving the hex nipple in the block
(Hava a rag handy as there may be an amount of hydraulic oils leakage)
Fit assembly

Refit washer and quick male connect fitting

Fit PEWeldBank Transducer




Assembly available from PE
Weld Bank reseller


info@peweldbank.com

Appendix 1d +GF+ TM Series

N.B. first ensure that there is no pressure in system.
 Remove male quick connect hydraulic coupling from control box
 Fit TBC
 Re-Fit male coupling to "TBC"
 Fit "TBC"
 Fit PEWeldBank Transducer to TBC



TBC








Appendix 1e Technodue PT 160-500

N.B. first ensure that the power is disconnected & there is no pressure in system.

Remove lever from valve
Remove top cover plate
Remove lower cover plate

Remove hydraulic hose from port "A"
(Have a rag handy as a little oil may escape.)
Fit assembly into Port "A"


Replace hydraulic hose to Assembly
Fit a cable tie to frame
Replace lower cover plate
Replace top cover plate
Replace lever to valve



Assembly available from PE
Weld Bank reseller

Appendix 1f Dixon EHF 450 & 630

N.B. first ensure that the power is disconnected there is no pressure in system.
Remove 1/4" plug
(have a rag handy as there may be an amount of hydraulic oil leakage)
Fit Test point 20 assembly with 1/4" male tapered fitting, Use Teflon or hydraulic thread sealant.



Assembly available from PE Weld Bank reseller

Test 20 with 1/4" BSPT adaptor

Appendix 1g Worldpoly WHD Control box

N.B. first ensure that the power is disconnected there is no pressure in system.

Remove 1/4" plug or transducer
(have a rag handy as there may be an amount of hydraulic oil leakage)
Fit Test point 20 assembly with 1/4" male tapered fitting,. Use Teflon or hydraulic thread sealant.



Assembly available from PE
Weld Bank reseller


Test 20 with 1/4" BSPT adaptor
(Item # Test Point 002)

Please contact your local hydraulics company or PEWeldBank reseller for fittings.


The following is a guide, we will add to this as more information becomes available.

Hydraulic Test Port Tee Identification


"BSPT" Male x BSPP Female Swivel BSPP Test Port Tee				
Line No	Part Number	Description	OD mm (a)	Price
1	BTM-BSF-BPF-0404	1/4 BSPT M/F Test 1/8 BSPP	13.03±	
2	BTM-BSF-BPF-0606	3/8 BSPT M/F Test 1/8 BSPP	16.50±	
3	BTM-BSF-BPF-0808	1/2 BSPT M/F Test 1/8 BSPP	20.59±	
4	BTM-BSF-BPF-1212	3/4 BSPT M/F Test 1/8 BSPP		
5	BTM-BSF-BPF-1616	1 BSPT M/F Test 1/8 BSPP		




"JIC" Male x JIC Female Swivel BSPP Test Port Tee				
Line No	Part Number	Description	OD mm (a)	Price
6	JIM-JIF-BPF-070702	7/16 JIC M/F Test 1/8 BSPP	10.97±	
7	JIM-JIF-BPF-090902	9/16 JIC M/F Test 1/8 BSPP	14.13±	
8	JIM-JIF-BPF-121202	3/4 JIC M/F Test 1/8 BSPP		
9	JIM-JIF-BPF-141402	7/8 JIC M/F Test 1/8 BSPP		
10	JIM-JIF-BPF-171702	1-1/16 JIC M/F Test 1/8 BSPP		
11	JIM-JIF-BPF-212102	1-5/16 JIC M/F Test 1/8 BSPP		



ORFS Male x JIC Female Swivel BSPP Test Port Tee				
Line No	Part Number	Description	OD mm (a)	Price
13	ORM-ORF-BPF-0909	9/16 ORFS M/F Test 1/8 BSPP		
14				
15	G-M0914	NIPPLE 9/16 JIC X 14 METRIC		
16	A-J-0609	ADAPTOR BSPT X 9/16 JIC M/F		
17				
18				



BSPP Male x Test 20 Male				
Line No	Part Number	Description	OD mm (a)	Price
19	BPM-TEST-0220	** 1/8 BSPPM x TEST 20 M	9.60±	
20	BPM-TEST-0420	1/4 BSPPM x TEST 20 M	10.90±	
21	BPM-TEST-0620	3/8 BSPPM x TEST 20 M	13.05±	
22	BPM-TEST-0820	1/2 BSPPM x TEST 20 M		



** Suits above Test Port Tees

Test 20 Bulk Head Coupling & hose			
Line No	Part Number	Description	Price
23	432-5612	Test 20 Bulk Head Coupling	
24	Test 20 hose x 400mm	Test 20 hose x 400mm	



Misc			
Line No	Part Number	Description	Price
25	BTM-BTM-0404	1/4" BSPTM x 1/4" BSPTM Nipple	
26	BTF-BTF-BTF-0404	1/4" BSPT Female Tee* TPT	

*branch tapped 1/4" Parallel

info@peweldbank.com

Please contact your local hydraulics company or PEWeldBank reseller for fittings.

The following is a guide, we will add to this as more information becomes available.

		Price		
1	Ritmo Basic 160-315	BTM-BSF-BPF-040402		Remove hose from pressure side of block and install these fittings
19	in steel case	BPM-TEST-0220		
1	Ritmo Basic 160-315	BTM-BSF-BPF-040402		Remove top from case install tee between hose and block, drill hole in case install 432-5612 fitting then connect with supplied hose
19	in Plastic case	BPM-TEST-0220		
23		432-5612		
24		Test 20 hose x 400mm		
1	Omisa Whiteline	BTM-BSF-BPF-040402		Remove hose from pressure side of block and install these fittings
19	Basic 160-315 in	BPM-TEST-0220		
15	Riyang (OLD)	G-M0914		Remove original nipple and Fit these fittings under accumulator and swing down on 45 degrees
16	Silver machine	A-J-0609		
7		JIM-JIF-BPF-090902		
19		BPM-TEST-0220		
7	Worldpoly	JIM-JIF-090902		Remove hose that connects to block from gauge and install these fittings
19	160-315 WHD160/315	BPM-TEST-0220		
21	Dixon	BPM-TEST-0420		Remove Male Quick connect and install these fittings refit male quick connect
25	EHF225 & 355	1/4" BSPTM x 1/4" BSPTM N		
26		1/4" BSPT Female Tee TPT		

Technodue



Appendix 2

Updating Sensor Firmware

www.PEWeldBank.com


info@peweldbank.com

Updating Sensors Firmware


Temperature Sensors V 1.0.9 and Pressure Sensors V 1.3.9 or earlier cannot be updated and must be returned to Flowlogix Pty Ltd for update.

Ensure that Bluetooth is enabled on your smartphone / tablet. Follow the prompts

1. Click **Dropdown Menu**




2. Click **Settings**




Updating Sensors Firmware

3. Click **Sensors**



4. Click **sensor**




5 Click **Update Firmware**



6 Click **Start Update**





Updating Sensor Firmware



7. Firmware updated

5 Click **Finish**





Appendix 3

Connection to Heater Plate via PT100 internal sensor

www.PEWeldBank.com

info@peweldbank.com



The Sensors dated March 2022 and later allow for connection to the Butt welding machines heater plate internal PT100 probe (where available)

Many machines have provision to plug in a data logger or temperature sensor. i.e. Ritmo, Worldpoly and GF, in most cases this may be used to connect to PE Weld Bank

McElroy and Dixon

Many McElroy and Dixon heater plates have a small temperature gauge inserted into the heater plate this can be removed and a PT100 probe inserted for connection directly to PEWeldBank

Please note:

The sensor probe (PT100) for the “Fixed Point Sensor” is located internally, close to the centre of the heater plate.

It is normal for it to read at a higher temperature than the “Surface Temperature Probe”.

Zone 1 to 4, Front and Back represent Surface Temperature including the Average.

Fixed Point Sensor represents heater plate internal temperature.

Heater Plate Target (° C)		215-235
	Front	Back
Zone 1	226	226
Zone 2	226	228
Zone 3	227	228
Zone 4	226	228
Average	226.81	
Fixed Point Sensor	240-242	

At commencement of weld
Measured during Phase 1 and 2

The PEWeldBank App allows the user to test the surface temperature at the start of “Every Day” or before “Every Weld”

If the user selects “Every Day” the app will ask for acceptance of previous check before allowing the user to continue the weld process.



This 1m long lead is included. One end is to plug into the Fixed sensor port (3.5mm 4 pole) the other end will plug into most Ritmo Basic and Delta model machines (5.5 x 2.1mm DC Barrel plug).



This 1m long lead is included. One end is to plug into the Fixed sensor port (3.5mm 4 pole) the other end has 4 wires allowing fitment of you own plug to suit your machine. (Red = FORCE —, White = RTD —, Green = RTD +, Black = FORCE +. For connection to 2 wire probe join [Red+White] & [Green+Black]

For connection to your machine, plugs can be purchased from your local electronics supplier, these are examples of plugs that are compatible to many Worldpoly and GF machines, you will need to contact your machine supplier for wiring diagrams



GF example



Worldpoly example



This lead is compatible to many Dixon and McElroy machines where you can remove the existing small dial thermometer and replace with this PT100 probe. (these can be made to order)

Appendix 4

User Hierarchy:

PE Weld Bank User Heirarchy			
	SUPER ADMIN* / WELDER	ADMIN / WELDER	WELDER
Person that initially set up system	Yes	No	No
Edit Company Details	Yes	No	No
Maintain Credit Card Details	Yes	No	No
Adding / Deleting / Pairing Sensors	Yes	Yes	Yes
Adding / Deleting / Editing: - Users - Projects - Butt Welding Machinery - Electrofusion Machinery - Setting preferences for: - OH&S check list - Heater Plate Temperture Recording - Custom Weld Number	Yes	Yes	No
Reviewer: - Approve / Reject Welds	Yes	Yes	No
Select: - Projects - Machines - Welding Standards - Conduct Welding	Yes	Yes	Yes

N.B. App system settings are device based not user based,
i.e. if user was to log into a different device the settings may not be correct
for this user.

*To change Super admin user the Super admin must send an email to
info@peweldbank.com and nominate the new Superadmin user from the
user list

Note: If a user's Level is changed they MUST logout and log back into app for changes to take
place.




Appendix 5
Unsubscribe or
Resubscribe
PE Weld Bank
FMS

www.PEWeldBank.com
info@peweldbank.com

To unsubscribe from PE Weld Bank FMS


Log onto PEWeldBank .com



Forgotten your username? send an email to info@peweldbank including your first and last name requesting your username.


Forgotten your password ? Click on forgot password, you will be sent a temporary password to your email address (check spam folder)

When you have this information Sign in



info@peweldbank.com


Click on Settings



Click on Cancel Subscription

This will immediately unsubscribe your account.

To renew again simply click on this button again and you will be able to re access your account.





Appendix 6

Re Subscribing or

Changing Credit Card


Details

www.PEWeldBank.com

info@peweldbank.com

To Change Credit Card Details in PE Weld Bank FMS


Log onto PEWeldBank.com



Forgotten your username? send an email to info@peweldbank including your first and last name requesting your username.


Forgotten your password? Click on forgot password, you will be sent a temporary password to your email address (check spam folder)

When you have this information Sign in




info@peweldbank.com

Click on Settings



Click on Re Subscribe or Edit
Here you will be able to re subscribe or change card details.





Appendix 7

Reviewing welds

www.PEWeldBank.com

info@peweldbank.com

Welds Flagged as “For Review”

PEWeldBank does not reject any welds, it simply asks for the reviewer to carry out further inspection of the weld.

Some welds may not be FMS Accepted due to time, pressure or temperature variations, see examples below.

Please also note where heat soak pressure is dropped to ZERO, PEWeldBank cannot always detect a change in pressure when the heater plate is removed, therefore not allowing accurate timing, in this case it must rely on verification by the reviewer to inspect and decide whether to accept the weld or reject it.

Reviewing welds not FMS approved




PEWeldBank PEWeldBank Individual Weld Report

Date	Weld Number	Custom Weld Number	Start Time	Ambient Temp	Status
03-05-2024	202405031154812386	1134	11:54	24.4° C	For Review

Project Details

Project Name	Job Number	Project Contact Details
[REDACTED]	JB1061	[REDACTED]


Weld Details	Required	Actual	
P1 bead-up pressure	14-18.8	15-16.7	bar
t1 bead-up size	Until indication of bead	23.00	mm / Seconds
P2 heat soak pressure	0.0-4.0	0.0-0.7	bar
t2 heat soak time	57-69	~63	Seconds
t3 heater plate removal time	≤6	≤6	Seconds
t4 time to achieve fusion jointing pressure	Not Specified	Not Specified	Seconds
P3 fusion jointing pressure	14-18.8	0-16.9	bar
t5 cooling time in machine under pressure	≥02:28	02:28	Min:Sec




Reviewing welds not FMS approved

Using the weld chart feature, measure the heat soak time by moving your cursor over the start and finish of heat soak. In this example it is 84s, whereas in the weld details it allows up to 69 seconds plus 6s for heater plate removal equals 75s therefore the heat soak was approximately 9s too long (s = seconds)

Weld Chart - 202405031154812386




Weld Chart - 202405031154812386



Weather resistant modification

If you are experiencing extreme weather conditions a simple modification may help.

Drill a 5.5mm hole in the sensor set case and leave the sensor inside, this will further protect the unit from dust , snow etc.





For further information:

Please contact PEWeldBank:

Email: info@PEWeldBank.com

Please note that our sales and support office is based in Melbourne Australia, we will respond to all enquiries as soon as possible, however we have a number of resellers worldwide that may be able to assist you. See our website for your nearest reseller.

www.peweldbank.com/reseller